EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L5	137	(15/340.2).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 10:48
L6	1	5 and excitation	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 10:48
L7	0	5 and excit$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 10:49
L8	16	5 and voltage	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 12:07
L9	3	"6848147"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 12:08
S1	135	(15/340.2).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/12/01 10:48
S2	137	(15/340.2).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 12:47

S3	49	("1356663"|"1447814"|"1914834"|"1953340"|"20020170137"|"20040000023"|"20040134019"|"20050015918"|"20050071056"|"3074089"|"3100907"|"3896892"|"3942604"|"4052767"|"4099291"|"4111372"|"4245370"|"4268769"|"4384386"|"4479078"|"4955106"|"5030864"|"5056175"|"5077823"|"5115537"|"5445886"|"5548173"|"5831261"|"5918728"|"5923111"|"5940927"|"5944635"|"5974622"|"6102022"|"6108862"|"6169258"|"6206181"|"6323570"|"6400048"|"6449792"|"6484352"|"6658692"|"6757934"|"6848147"|"7000285"|"7043794"|"7062816"|"7076830"|"RE34286").PN.	US-PGPUB; USPAT	OR	OFF	2006/11/30 15:14
S4	114	("1356663"|"1447814"|"1914834"|"1953340"|"20020170137"|"20040000023"|"20040134019"|"20050015918"|"20050071056"|"3074089"|"3100907"|"3896892"|"3942604"|"4052767"|"4099291"|"4111372"|"4245370"|"4268769"|"4384386"|"4479078"|"4955106"|"5030864"|"5056175"|"5077823"|"5115537"|"5445886"|"5548173"|"5831261"|"5918728"|"5923111"|"5940927"|"5944635"|"5974622"|"6102022"|"6108862"|"6169258"|"6206181"|"6323570"|"6400048"|"6449792"|"6484352"|"6658692"|"6757934"|"6848147"|"7000285"|"7043794"|"7062816"|"7076830"|"RE34286").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 12:14
S5	55	("1356663"|"1447814"|"1914834"|"1953340"|"20020170137"|"20040000023"|"20040134019"|"20050015918"|"20050071056"|"3074089"|"3100907"|"3896892"|"3942604"|"4052767"|"4099291"|"4111372"|"4245370"|"4268769"|"4384386"|"4479078"|"4955106"|"5030864"|"5056175"|"5077823"|"5115537"|"5445886"|"5548173"|"5831261"|"5918728"|"5923111"|"5940927"|"5944635"|"5974622"|"6102022"|"6108862"|"6169258"|"6206181"|"6323570"|"6400048"|"6449792"|"6484352"|"6658692"|"6757934"|"6848147"|"7000285"|"7043794"|"7062816"|"7076830"|"RE34286").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/11/30 12:14

S6	64	("1356663" | "1447814" | "1459946" | "1465285" | "20010039691" | "20020170137" | "20040134019" | "20040134020" | "20040135537" | "20050015918" | "20050071056" | "2619209" | "2814063" | "2950772" | "3218876" | "3220043" | "3451495" | "3581591" | "3618687" | "3823791" | "3854164" | "3896892" | "3938216" | "3942604" | "4052767" | "4111372" | "4249281" | "4342369" | "4347643" | "4434865" | "4615071" | "4624027" | "4766640" | "5042109" | "5056175" | "5077823" | "5115537" | "5269042" | "5285550" | "5335740" | "5339916" | "5406674" | "5455886" | "5504971" | "5831261" | "5944635" | "5974622" | "6061869" | "6102022" | "6108862" | "6169258" | "6449792" | "6741051" | "RE34286").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/11/30 13:08
S7	64	("1356663" | "1447814" | "1459946" | "1465285" | "20010039691" | "20020170137" | "20040134019" | "20040134020" | "20040135537" | "20050015918" | "20050071056" | "2619209" | "2814063" | "2950772" | "3218876" | "3220043" | "3451495" | "3581591" | "3618687" | "3823791" | "3854164" | "3896892" | "3938216" | "3942604" | "4052767" | "4111372" | "4249281" | "4342369" | "4347643" | "4434865" | "4615071" | "4624027" | "4766640" | "5042109" | "5056175" | "5077823" | "5115537" | "5269042" | "5285550" | "5335740" | "5339916" | "5406674" | "5455886" | "5504971" | "5831261" | "5944635" | "5974622" | "6061869" | "6102022" | "6108862" | "6169258" | "6449792" | "6741051" | "RE34286").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/11/30 13:11
S8	0	("7076830").URPN.	USPAT	OR	OFF	2006/11/30 13:11

S9	60	("1356663" | "1447814" | "1459946" | "1465285" | "20010039691" | "20020170137" | "20040134019" | "20040135537" | "20050071056" | "2619209" | "2814063" | "2950772" | "3218876" | "3220043" | "3451495" | "3581591" | "3618687" | "3823791" | "3854164" | "3896892" | "3938216" | "3942604" | "4052767" | "4111372" | "4249281" | "4342369" | "4347643" | "4434865" | "4615071" | "4624027" | "4766640" | "5056175" | "5077823" | "5115537" | "5285550" | "5335740" | "5339916" | "5406674" | "5455886" | "5504971" | "5831261" | "5944635" | "5974622" | "6061869" | "6102022" | "6108862" | "6169258" | "6449792" | "6741051" | "RE34286").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/11/30 13:14
S10	1111	15/340.1, "340.3"	US-PGPUB; USPAT	OR	OFF	2006/11/30 13:16
S11	973	(15/340.1,340.3).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 13:16
S12	1071	(15/340.1,340.3,340.2).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 13:16
S13	2203	(15/339,319).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 13:16
S14	877	(15/319).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 13:17

S15	2593	(15/350-353).CCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 13:17
S16	2547	S15 not S14	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 13:17
S17	2400	S16 not S13	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 13:17
S18	2252	S17 not S12	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/30 14:05
S19	23977	motor same armature same magnet	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/30 14:05
S20	4685	motor same armature same magnet	USPAT	OR	ON	2006/11/30 14:13
S21	56	S15/$.ccls. and (motor same armature same magnet)	USPAT	OR	ON	2006/11/30 14:05
S22	63	motor same armature same magnet same Hall same brushless	USPAT	OR	ON	2006/11/30 14:25
S23	15	motor same armature same (Hall adj sensor) same brushless	USPAT	OR	ON	2006/11/30 15:01
S24	5	motor same armature same (Hall adj sensor) same gear	USPAT	OR	ON	2006/11/30 15:02
S25	33	motor same armature same Hall same gear$3	USPAT	OR	ON	2006/11/30 14:26
S26	43	motor same armature same Hall same gear$3	US-PGPUB; USPAT	OR	ON	2006/11/30 14:26

S27	138	motor same armature same (Hall) same shaft	USPAT	OR	ON	2006/11/30 15:01
S28	32	motor same armature same (Hall adj sensor) same shaft	USPAT	OR	ON	2006/11/30 15:47
S29	58	motor same armature same (Hall adj2 sensor) same shaft	USPAT	OR	ON	2006/11/30 15:47
S30	138	motor same armature same (Hall -effect adj sensor) same shaft	USPAT	OR	ON	2006/11/30 16:03
S31	106	S30 not S28	USPAT	OR	ON	2006/11/30 15:49
S32	60	S31 and gear$4	USPAT	OR	ON	2006/11/30 15:49
S33	1	motor same armature same (Hall adj effect adj sensor) same shaft same bearing	USPAT	OR	ON	2006/11/30 16:03